
UNCLASSIFIED

AD NUMBER AD838004 LIMITATION CHANGES TO: Approved for public release; distribution is unlimited. FROM: Distribution authorized to DoD only; Test and Evaluation; APR 1968. Other requests shall be referred to Army Materiel Command, Attn: AMCPM-IR, PO Box 209, Main Office, St. Louis, MO 63166. **AUTHORITY** usaavscom ltr, 12 nov 1973





AD RDTE Project No. 1X141807D174 USAAVCOM Project No. 68-03 (66-06) USAAVNTA Project No. 68-03 (66-06)

ENGINEERING FLIGHT TEST OF THE AH-1G HELICOPTER EQUIPPED WITH THE XM-28 CHIN TURRET WITH ONE 7.62 MM AUTOMATIC GUN (M-134) AND ONE 40MM GRENADE LAUNCHER (XM-129) HYBRID

PHASE B . PART 5

FINAL REPORT

PETER V. PASSINISI

WILLIAM J. CONNOR

SP5 US ARMY CW4, AV US ARMY

PROJECT ENGINEER

PROJECT OFFICER/PILOT

APRIL 1968 STATIMENT #4 UNCHASSIFIED

Each transmittal of this document outside the papartment of Command Defense must have prior approval of Linny Material Command Attn: AMCPM-IR
P.O. Box 209 Main Office
St. Louis, Inissouri 63166

US ARMY AVIATION TEST ACTIVITY EDWARDS AIR FORCE BASE, CALIFORNIA 93523

DDC Availability Notice

US military agencies may obtain copies of this report directly from DDC. Other qualified users shall request through the Commanding General, Hq, US Army Materiel Command (USAMC), ATTN: AMCPM-IR, St. Louis, Missouri 63166.

Reproduction Limitations

Reproduction of this document in whole or in part is prohibited except with permission obtained through the Commanding General, Hq, USAMC, ATTN: AMCPM-IR, St. Louis, Missouri 63166. DDC is authorized to reproduce the document for United States Government purposes.

Disposition Instructions

Destroy this report when it is no longer needed. Do not return it to the originator.

Trade Names

The use of trade names in this report does not constitute an official endoresement or approval of the use of the commerical hardware and software.

Distribution

This document may be throber distributed by any older only with specific print approved obtained through the Community General, H. SMC, ATTN: AMCPRIER, St. E-uit Missoury 63166.

RDTE Project No. 1X141807D174 USAAVCOM Project No. 68-03 USAAVNTA Project No. 68-03

ENGINEERING FLIGHT TEST OF
THE AH-1G HELICOPTER EQUIPPED WITH
THE XM-28 CHIN TURRET WITH ONE 7.62mm
AUTOMATIC GUN (M-134) AND ONE 40mm GRENADE
LAUNCHER (XM-129)-HYBRID

PHASE B
PART 5

FINAL REPORT

PETER V. PASSINISI SP5 US ARMY PROJECT ENGINEER WILLIAM J. CONNOR CW4, AV US ARMY PROJECT OFFICER/PILOT

APRIL 1968

US ARMY AVIATION TEST ACTIVITY EDWARDS AIR FORCE BASE, CALIFORNIA 93523



ABSTRACT

Part 5 of the AH-1G helicopter Phase B test was conducted at Yuma Proving Ground, Yuma, Arizona, from 6 through 9 February 1968 by the US Army Aviation Test Activity, Edwards Air Force Base, California. The test consisted of firing the XM-28 chin turret, with one 7.62 millimeter automatic gun (M-134) and one 40 millimeter grenade launcher (XM-129) to determine the weapons system's effect on the stability and control characteristics of the helicopter. No safety of flight restrictions resulted from firing this system within the flight envelope. Correction of four deficiencies is mandatory to provide acceptable mission effectiveness and safety. These deficiencies are the inadequate forward visibility from the pilot's cockpit due to the N-9A gunsight installation, the lack of a fire warning system, the lack of a standby generator for IFR flight, and link jam malfunctions of the minigun during symmetrical pull-out maneuvers. Fifteen shortcomings, for which correction is desirable, limit mission effectiveness. The reliability of the weapons system was questionable and service type testing should be conducted prior to system acceptance. Correction of the deficiencies is mandatory and should be tested prior to deployment. Shortcomings, for which correction is desirable, should be corrected on a high priority basis.

FOREWORD

During the conduct of the AH-IG helicopter Phase B, Part 5 test at Yuma, Arizona, the test helicopter with installed special instrumentation was maintained by Bell Helicopter Company personnel. Data reduction assistance was also provided by Bell Helicopter Company personnel. US Army firing ranges, hanger and office facilities at Yuma Proving Ground, Arizona were utilized.

TABLE OF CONTENTS

INTRODU	CTION
Test Descr Scope	round
	ology
RESULTS	AND DISCUSSION
Gen Yaw	g Tests eral and Pitch Axis Reactions
Pil Cop Missi	it Evaluation ot's Cockpit! ilot/gunner's Cockpit! on Suitability
F E Wea	craft ire Warning System! lectrical System
Air	enance Suitability craft1 pons System1
CONCLUS	IONS
Defic:	al1 iencies and Shortcomings Affecting Mission omplishment1
RECOMME	NDATIONS1
APPENDI	XES
I. II. IV.	References
77	Toot Instrumentation

INTRODUCTION

BACKGROUND

1. The XM-28 chin turret was designed to accommodate three basic weapons' configurations. These configurations are: (1) two 7.62 millimeter automatic guns M-134 (miniguns); (2) two 40 millimeter grenade launchers XM-129 (launchers); and (3) one 7.62 millimeter automatic gun M-134 and one 40 millimeter grenade launcher XM-129. The third configuration, hereafter referred to as the Hybrid, is capable of operating with either gun on the right or left side of the turret. Configurations (1) and (2) were previously flight tested by the US Army Aviation Test Activity (USAAVNTA) and the results of these tests are contained in references 1 and 2, appendix I. This test, directed by references 3 and 4, appendix I, was conducted with the Hybrid configuration and completes the engineering flight tests of the XM-28 chin turret.

TEST OBJECTIVES

- 2. The objectives of this test were to provide flight test data to:
- a. To assist in determining if the contractor's proposed flight envelope should be used by Army pilots for future service tests, logistic tests, or operational tests.
- b. Define any helicopter or weapons system deficiencies to allow early correction.
- c. Provide a basis for evaluation of subsequent changes incorporated to correct deficiencies.
- d. Determine the aircraft and weapon system capabilities to perform their intended mission.

DESCRIPTION

3. The AH-1G helicopter, manufactured by Bell Helicopter Company, is a tandem, two-place, high speed conventional helicopter with a two-bladed door hinge type main rotor and a conventional antitorque rotor. The helicopter was designed specifically for the attack mission from a land based operation and is capable of operating under day/night visual or instrument flight conditions. The AH-1G is equipped with a three axes stability and control augmentation system to improve helicopter stability

and control characteristics. The powerplant is a Lycoming T53L-13 turbo-shaft engine rated at 1400 shaft horsepower (shp) at sea level under standard day static conditions. The engine is pilot limited to 1100 shp due to the maximum torque limits of the helicopter's main transmission. The distinctive features of the AH-1G are the narrow fuselage (36 inches), the stub midwings with four external stores stations and the integral XM-28 chin turret. The flight control system is a positive mechanical irreversible type with conventional helicopter controls in the pilot's aft cockpit. The copilot/gunner's controls in the forward cockpit consist of conventional antitorque pedals and sidearm collective and cyclic controls. An electrical force trim system is connected to the cyclic and directional controls to induce artificial feel and to provide positive control centering. A synchronized elevator is used to improve static longitudinal stability and increase the center of gravity (C.G.) range. The test helicopter, AH-IG serial number 66-15283, was representative of production helicopters. A complete aircraft description is contained in references 5 and 6, appendix I.

The XM-28 chin turret with the Hybrid weapons system incorporates one 7.62 millimeter automatic gun (M-134) and one 40 millimeter grenade launcher (XM-129). The system is hydraulically and electrically operated and is fully flexible. A copilot/gunner's sighting station is provided for the purpose of tracking and firing the turret guns. Maximum turret positions are 107.5degrees left and right azimuths, 50-degrees depression and 12degrees to 17.5-degrees elevation. The pilot can control and fire the weapons system from a forward stowed position, only. Rates of fire of the 7.62 millimeter automatic gun are 1300 and 4000 rounds per minute. Either rate may be selected by the copilot/gunner or pilot. Continuous fire is limited to 6 second bursts by an automatic burst limiter to prevent overheating of the weapon. The 40 millimeter grenade launcher has a rate of fire of 400 rounds per minute and is automatically limited to 10 second bursts. Although separate switches are provided for selecting minigun or launcher fire the system is designed to fire one weapon at a time. Should both switches be depressed simultaneously an overriding feature will allow only the minigun to fire. A full complement of ammunition consists of 4000 rounds of 7.62 millimeter and 300 rounds of 40 millimeter.

SCOPE OF TEST

5. Flight testing of the Hybrid weapons system was conducted to evaluate the system's firing effects on the stability and control characteristics of the AH-IG helicopter. Weapon configurations and turnet positions tested are presented in tables 1 and 2.

Table 1. Hybrid Configurations.





Table 2. Turret Positions.



6. Four flights were conducted for a total of 7.1 hours of flying time. The flight restrictions and operating limitations stated by Flight Standards Office, AVCOM were observed during this test and are summarized in appendix III. A safety of flight release (ref 7, app I) was issued by US Army Aviation Materiel Command (USAAVCOM), St. Louis, Missouri. During the test approximately 15,500 rounds of 7.62 millimeter and 650 rounds of 40 millimeter ammunition were expended. Test C.G. locations are presented in figure 1, appendix II. An airspeed calibration for this aircraft was conducted during the Phase B, Part III test (ref 1, app I) and the results are presented in figure 21, appendix II. Flight test conditions are presented in table 3.

Table 3. Flight Test Conditions.

Configuration	Weapon	Airspeed Turret Position (KCAS)
Δ	Minigun	Hover 1, 2, 3, 7, 8, 9
		130 1, 2, 3, 4, 5, 6, 7, 9 176 1, 2, 3, 4, 5, 6, 7, 9
3	Minigun	Hover 8
		1, 2, 3, 4, 5, 6, 7, 9
A.	Leuncher	130 1, 2, 3, 4, 5, 6, 7, 9

Gross Weight Range: 7360 to 8480 1b; C.G. Range: 196.6 to 199.3 in FRL; Density Alticude: 1500 to 3400 ft; Rotor Speed: 324 rpm. Instrumentation pods installed on outboard wing stations.

METHODS OF TEST

- 7. Stability and control data were obtained using standard engineering flight test methods. All firing was initiated from steady heading, balanced flight at stabilized airspeed of 130 KIAS (a representative attack airspeed), 180 KIAS (V_{limit}) or from hovering flight out of ground effect (OGE). The tests were conducted at an aft C.G. and light gross weight to attain maximum reactions on stability and control. The majority of the tests were conducted with the mirigun firing at the high rate since previous tests (ref 1 and 2, app I) show greater aircraft reactions when firing this weapon.
- 8. Oscillograph and cockpit data were recorded with the flight controls fixed and free. The control-fixed method was used to evaluate the effects of the weapons firing upon the stability and control parameters and the control-free method was used to evaluate the pilot's ability and workload in maintaining the initial trim flight condition. Qualitative ratings of flying qualities are based on the Pilot Rating Scale (PRS) presented as appendix IV. A list of test instrumentation is contained in appendix V.
- 9. Various factors, such as turret position, airspeed and physical location of the weapon, i.e. configuration A or B, affect the aircraft's reaction to the single firing of dual mounted weapons. In an attempt to isolate these factors, the test was conducted in the sequence listed below.

- a. Fire all turret positions at one airspeed.
- b. Vary airspeed and fire one turret position.
- c. Change weapon configurations and spot check selected turret positions.

CHRONOLOGY

10. The chronology of this test is as follows:

Test directive received	20	October	1967
Test helicopter received	6	February	1968
Flight tests commenced	6	February	1968
Flight test completed	9	February	1968
Draft report submitted	4	March	1968
Final report forwarded		April	1968

RESULTS AND DISCUSSION

FIRING TESTS

General

- 11. Firing tests were conducted in the test configurations listed in paragraphs 5 and 6 to determine the effects of the XM-28 Hybrid weapons system firing on the stability and control characteristics of the AH-1G helicopter. Yaw and pitch axes firing reactions were small at all conditions tested and required only minor pilot compensation to maintain the desired flight condition. Roll axis firing reactions were also small, however, the aircraft exhibited an oscillatory roll response to all firing and considerable pilot compensation in lateral control was required to maintain the initial trim flight condition. Although the lateral reactions and control corrections were insignificant regarding safety of flight, the pilot effort required to damp the roll oscillation will have a detrimental effect on rocket gunnery where a stable gun platform is necessary for firing accuracy.
- 12. The effects of the weapons firing (flight controls fixed) on the stability and control parameters are presented as time histories in figures 2 thru 19, appendix II. Figures 2 thru 15 are the results of firing the minigun in configurations A and B. Figures 16 thru 19 are the results of launcher firing in configuration A. All extreme minigun turret positions are presented with the exception of 90-degree left azimuth, full down depression. In this position a trigger switch malfunction prevented the copilot/gunner from firing the minigun at the high rate of fire. Previous testing (ref 1, app I) indicated that no safety of flight restrictions existed from firing two miniguns simultaneously from this turret position.

Yaw and Pitch Axes Reactions

13. Yaw and pitch axes reactions to the minigun and launcher firing were determined for the turret positions and flight conditions listed in tables 1, 2 and 3. The rates at 0.5 seconds after start of firing (a representative pilot reaction time) and the maximum rates that occurred during the firing sequence are presented in table 4. Under all conditions tested the yaw and pitch axes reactions were very small and should not create a target tracking problem to the copilot/gunner or the pilot (PRS A3, app IV).

Table 4. Yaw and Pitch Rates.

Aarspeed Weapon KCAS and	Yaw Rates 0/sec Pitch Rates 9/sec
Turret Position	Rate at Maximum Rate Rate at Maximum Rate 0.5 (sec) and time (sec) (sec)
128 Minigun 0° aminuth full up elevation	2.0 down 2.0 down; 0.5 sec
Minigun 90° right, 0° elevation	2.0 left
Hover Minigun O asimuth O alevation	3.2 right, 2.25

- 14. The pilot compensation for longitudinal and directional control to maintain steady heading, balanced flight is presented as a time history in figure 20, appendix II. With the minigun firing at a turret position of 90-degrees right azimuth, full up elevation, the yaw rates and attitudes were arrested and stabilized within 4 seconds with two inputs of longitudinal control and one input of pedal control. The reactions were easily compensated for by the pilot without over controlling (PRS A3).
- 15. Yaw axes reactions resulting from firing the minigun from a position off the longitudinal axis of the aircraft were also small. The maximum yaw reactions resulting from asymmetric firing occurred in hovering flight and were not objectionable. Hover firing tests were conducted with the minigun in configuration A and B and no significant changes in asymmetric firing reactions were noted. The yaw reaction obtained at 128 KCAS was .2 degrees per second left yaw rate and was not perceptible to the pilot (PRS Al, app IV).

Roll Axis Reaction

16. Roll axis reactions (flight controls fixed) to the minigun and launcher firing are included in figures 2 thru 19, appendix II. Under all firing conditions tested, the roll rates were small and did not cause any unsafe flight condition. The maximum

roll rate was 6-degree/sec right and occurred after 1 second of minigun firing from a turnet position of 90-degree right azimuth, full down depression.

17. Although the roll rates were small, the data indicated that regardless of weapon, turret position, or airspeed, firing caused a roll oscillation. This indicated weak roll damping. The pilot effort required to damp this oscillatory roll response is presented in figure 20, appendix II. The data show numerous inputs of lateral control as the pilot attempted to maintain steady-heading, balanced flight. Although the pilot was able to return the aircraft to the original trim attitude in 3.5 seconds, continuous lateral corrections were required throughout the firing sequence to damp the roll oscillation. Stabilizing the helicopter in roll attitude required considerable pilot compensation and even greater pilot effort would be required if the turret weapon was traversed while firing (PRS A5, app IV). The pilot effort required to maintain a desired roll attitude adversely affects rocket gunnery, in that full pilot attention must be given to gunnery techniques and to the tactical situation in order to achieve satisfactory accuracy. An increase in lateral damping is desirable for improved operation and mission accomplishment.

COCKPIT EVALUATION

Pilot's Cockpit

18. With the pilot's seat in upper most position, the pilot's forward visibility is obstructed by the N-9 pilot's gun sight. This restriction to forward vision is particularly noticeable during contour flying and the final portion of approaches to a landing. During normal approaches, where peripheral visual cues to the intended landing area are not available, the pilot must fly the aircraft in a 5 to 10-degree sideslip during the final portion of the approach to compensate for the visual obstruction (PRS A5, app IV). During autorotative approaches, this sideslip technique cannot be employed and the pilot cannot observe his intended landing area during the flare just prior to touchdown. Because of the reduced visibility, the pilot compensation required to perform an autorotative landing during daylight hours was excessive (PRS A6, app IV). During night operations, when visibility is already restrictive, it is doubtful that repeatable successful touchdown autorotations can be accomplished even under ideal conditions (PRS U7, app IV). An increase in forward cockpit visibility is mandatory for satisfactory operation and mission accomplishment. The

shortcomings noted in reference 1, appendix I, concerning the headphone jack cord and the smoke grenade dispensor switch have not been corrected and were still applicable.

Copilot/gunner's Cockpit

- 19. Entry and egress to the copilot/gunner's cockpit was difficult. The one single step is located 38 inches from ground level at a position too high for comfortable use. An individual of average size, wearing combat dress i.e. flak jacket, chest protector and sidearm; would require assistance from a ground crewman to gain entry to the cockpit. An additional lower step is desirable for improved entry and egress to the copilot/gunner's cockpit.
- 20. The copilot/gunner's cockpit was identical to the one evaluated in references 1 and 2, appendix I. The shortcomings noted in reference 1, appendix I, concerning sight interference, non distinct positions of the trigger switches and mislocation of functional switches have not been corrected and are still applicable.

MISSION SUITABILITY

Aircraft

Fire Warning System

21. A fire warning system is not provided on production AH-IG helicopters. Installation of a fire warning system is mandatory to accomplish the intended combat mission with a satisfactory degree of safety.

Electrical System

22. The AH-IG helicopter is equipped with one 300 amp generator. A generator failure will preclude satisfactory completion of an attack mission, and during instrument flight operations may preclude safe return of the aircraft. Incorporation of a standby generator is desirable for day/night visual operations and is mandatory for mission requiring instrument flight.

Weapons System

23. Prior to this test several stoppages of the minigun were encountered during tests by Bell Helicopter Company. The stoppages occurred when ammunition links jammed in the link ejection chute and prevented the weapon from firing. The link jams occurred

when the minigun was configured on the right side, with the turret position was 90-degree left azimuth, full down depression, and while maneuvering the aircraft in a high speed symmetrical pull-out and firing at the high rate of 4000 rounds/minute. This maneuver was repeated four times during this test using a low rate of fire (1300 round per minute). Stoppage occurred each time. Link jams were the cause of three malfunctions. The cause of the fourth stoppage was unknown. The weapons system contractor's representative stated that the probable reason this particular malfunction did not occur during the twin minigun testing (ref 1, app I) was the difference in link ejection chutes. A prototype link ejection chute was used during the twin minigun tests while a production link ejection chute was installed for this test. Correction of the link jam malfunction is mandatory for satisfactory operation and mission accomplishment.

24. During the conduct of this test 13 malfunctions occurred while expending 15,500 rounds of 7.62 millimeter ammunition and 650 rounds of 40 millimeter ammunition indicating poor reliability of the weapons system. Although a portion of these malfunctions could have been the result of defective ammunition and ammunition linkage this reasoning was not substantiated during this test. It is recommended that service testing be conducted prior to system acceptance to determine if the Hybrid weapons system's reliability is satisfactory for operation and mission accomplishment.

MAINTENANCE SUITABILITY

Aircraft

- 25. The following shortcomings noted in reference 1, appendix I, were not corrected and were still applicable.
- a. The 90-degree gear box and mount casting are not easily accessible for daily inspections.
- b. The lack of hand holds to assist in rotor head daily inspections.
- c. An inadequate amount of non-skid type material installed on the stub wings.
- d. The lack of main rotor droop stops to prevent main rotor head mast damage.
- e. The throttle linkage, electrical wiring and oil cooler are not easily accessible for daily inspections.

Weapons System

- 26. The 40 millimeter ammunition chute links, located closest to the weapon, wear excessively in comparison to the remainder of the chuting. Previous testing has indicated an ammunition chute service life of approximately 2,000 rounds. This service life could be extended considerably if the first four links of the chuting were constructed of heavier gauge metal. Correction is desirable for improved operation and mission accomplishment.
- 27. Two stoppages of the minigun were caused by crossover system jams. The latches on the crossover mechanism failed during both malfunctions and allowed 25 to 100 rounds of 7.62 millimeter ammunition to jam between the ammunition cans and the top of the ammunition compartment. An excessive amount of time (30 minutes to an hour) and considerable physical force with a long screwdriver and hammer was required to correct these malfunctions. Damage could easily occur to the weapons system and/or the aircraft because of the method in which the jam must be cleared. A redesign of the system to prevent the ammunition from leaving the container during a crossover malfunction is desirable for improved operation and mission accomplishment.
- 28. During this test the weapons system contractor's representative replaced the granade launcher drive cable after three weapon jams. The contractor's representative stated that from previous testing it was found that the cable could only withstand approximately three jams before breaking. An increase in the service life of the drive cable is desirable for improved operation and mission accomplishment.
- 29. The following deficiencies and shortcomings noted in references 1 and 2, appendix I, were not corrected and were still applicable.
- a. The ammunition feeder roll pins on the minigun had an excessively short service life.
- b. The lack of a guide for the minigun ammunition chute to prevent damage to chute during loading operations.
- c. The ammunition loading tool for the grenade launcher is inadequate.
- d. Separation of the teflon covering on the ammunition bay guide rails.
 - e. Excessive wear of grenade launcher's rear gun mounts.

CONCLUSIONS

GENERAL

- 30. The following conclusions were reached upon completion of firing tests of the XM-28 Hybrid installation on the AH-1G helicopter.
- a. No safety of flights restrictions resulted from firing the XM-28 Hybrid installation within the flight envelope (para 16).
- b. The intended mission of the AH-1G helicopter as a weapons platform is degraded by inadequate roll damping (para 17).

DEFICIENCIES AND SHORTCOMINGS AFFECTING MISSION ACCOMPLISHMENT

- 31. Correction of the following deficiencies is mandatory prior to further acceptance of the aircraft and/or acceptance of the weapons system.
- a. Inadequate forward visibility from the pilot's cockpit during contour flying and approaches (para 18).
 - b. Lack of a fire warning system (para 21).
 - c. Lack of a standby generator for instrument flight (para 22).
- d. Link jam malfunctions of the minigun during symmetrical pull-out maneuvers (para 23).
- 32. Correction of the following shortcomings is desirable for improved operation and mission accomplishment.
 - a. Inadequate roll damping (para 17).
- b. Excessive length of the pilot's headphone jack cord allows entanglement with the collective control (para 18).
- c. The XM-20 smoke grenade dispenser switch can only be operated when the Master Arm Switch is in "ARMED" position (para 18).

- d. Difficult entry and egress to the copilot/gunner's cockpit (para 19).
- e. When stowed, the flexible copilot/gunner's sight interferred with the gunner's right leg (para 20).
- f. The lead angle compensation switch and the gun selector switch, both located on the copilot/gunner's sight mounting, were unguarded and can be accidentally actuated (para 20).
- g. Lack of a standby generator for day/night visual flight operations (para 22).
- h. The 90-degree gear box and mount casting were not easily accessible for daily inspection (para 25a).
- i. The lack of hand holds to assist in rotor head daily inspections (para 25b).
- j. Inadequate amount of non-skid type material installed on the stub wings (para 25c).
- k. The lack of main rotor droop stops to prevent main rotor mast damage (para 25d).
- 1. The throttle linkage, electrical wiring and oil cooler were not easily accessible for daily inspections (para 25c).
- m. Short service life of the grenade launcher ammunition chute (para 26).
- n. Clearance of minigun crossover jams is time consuming to clear and clearance can result in damage to the weapons system and/or the aircraft (para 27).
- o. Short service life of the grenade launcher drive cable (para 28).


RECOMMENDATIONS


- 33. Service testing should be conducted prior to system acceptance to determine if the Hybrid weapons system's reliability is satisfactory for operation and mission accomplishment (para 24).
- 34. The deficiencies for which correction is mandatory should be corrected prior to further aircraft acceptance and/or acceptance of the weapons system.
- 35. The shortcoming for which correction is desirable should be corrected on a high priority basis.

APPENDIX I REFERENCES

- 1. USAAVNTA Final Test Report, Engineering Flight Test of the AH-1G (Hueycobra) Helicopter Equipped with the XM-28 Chin Turret with Twin XM-134 Miniguns, Phase B, Part 3," March 1968.
- 2. USAAVNTA Final Test Report, Engineering Flight Test of the AH-1G (Hueycobra) Helicopter Equipped with the XM-28 Chin Turret with Twin XM-129 40 mm Grenade Launchers, Phase B, Part 4." March 1968.
- 3. Letter, AMSAV-E(EF) to CO, USAAVNTA, SAVTE-P, Subject: "US Army Aviation Test Activity Participation in the AH-1G/ XM-28 Airworthiness Qualification Program," 20 October 1967.
- 4. Unclassified Message AMSAV-E(EF)-11-1368 to SAVTE-P, subject: "AH-1G/XM-28 Airworthiness Qualification Program," 15 November 1967.
- 5. Report No. 209-947-016, "Detail Specification for Model AH-1G Helicopter," Bell Helicopter Company, 11 July 1966.
- 6. TM 55-1520-221-10 Operator's Manual," Army Model, AH-1G Helicopter, Headquarters, Department of the Army," April 1967.
- 7. Priority Message, AMSAV-EF-2-1304, CG USAAVCOM to CO USAAVNTA, SUBJECT: "Safety of Flight Release for Phase B Testing AH-1G/ XM-28 Mixed Configuration," 5 February 1968.


APPENDIX II TEST DATA








No: 2 MINIGUN) FIRING 66- 15283 APPROXIMATE DENSITY ALTITUDE ROTOR SPEED CONFIGURATION ~ FT. ~ R.P.M 2800 324 INSTRUMENTATION NOTES: PODS OUTBOARD I TURRET POSITION 90° LEFT AZIMUTH FULL UP ELEVATION 2. MINIGUN FIRING AT HIGH RATE (4000 ROUNDS/MIN) 3. DENSITY ALTITUDE IS BASED ON UNCALIBRATED FREE AIR TEMPERATURE 4 ENGINE OUTPUT POWER APPROXIMATELY 760 SHAFT HORSE POWER FIRING S. CONFIGURATION A STOP UDE # 5 BECONDS 5 10






PODS OUTBOARD A PUBLIC HELTON PROBLEM	O. 3 INIGUN) FIRING G-15283 AFPROXIMATE ENSITY ALTITUDE	ROTOR SPEED RPM 824	CONFIGURATION	NOTES:
905-7 			PODS OUTBOARD	ZERO AZIMUTH POLL UP BLEVATION Z. MINIGUN FIRING AT HIGH RATE (4000 ROUNDS / M/N) E DENSITY ALTITUDE IS BASED ON UNCALIBRATED FREE AIR TEMPERATURE H. ENGINE OUTPUT POWER APPROXIMATELY 760 SHAFT HORSEPOWER
	STOP FIRIN			
DDE-7				






No: 4 MINIGUN) FIRING																									
N 66- 15288																									
APPROXIMATE						1																			
DENSITY ALTITUDE	1	≎7¢5	9.S		JE.C)		COM	JFI	SUR	AT	ON						•							
2500			24							IME	~ 4 ~ ~ ~	to the state of	unger 6 million pr	-	-			OTE	- depresent	-					
							. 1.	POI	25	OU	78	0	RD.	4		1 1	15	URF D'R JLL	161	IT I	AZI	MU	TH		
																	2. M	MIG	W	FI	RINE	S A	TH	A IN)
				1									The reservoir	1			3 DE	NSI	TY	AL	THE	Tu:	AA.T	SED	,
	-										1		Market France	-	h de g a mades		4 Et	iee Iei	NE-	ou	TP	UT	PO	WEF	
SN						•			1			•		a spanion to			51	PPR	T	HO	RSI	E PO	WE	R	
FIRING					1	į						,		1 1000		manus en de	5. C	ONF	764	IR A	TIG	> N	A		
		-									-			*	mer in water to the	p to super			-	ander temperature					
PITCH SCAS					1			1										4							
						to the American	=!.						-14	1					4	1					
Z-ROLL SCAS	S				1			1											1						
				*** * *				,										April 14							
						. !														i					
The second								ì						i				-	1: :	1					
Z PITCH RATE				. 1										1		n po metro de									
						•				and the state of t		· · · · · ·						-							
																		1							
																		1-	-	, .					
DE																									
																			111						
																			1-13						
																						1			
4 5 6 SECONDS		4			3			9			10														









Jo: MINI	GUN) FIRING								
	15289								
	APPROXIMATE	TOR SPEED	CONFI	SURATION					
	7FT.	~R.PM.							
I			\$1000 there is a productive pro-	MENTATION	NOT	ES: Ret i	105 T	DN	
9					250	RIGH O ELI	YATI	MUTH ON	
					RAT	E (#0	00 A0	AT HI	MM)
.					S DEN	BITY ED OF	UNC	AL/BA	PATE
					# ENG!	ME 01	T PUT	7 7%	24
					ENA	FT H	PERE	WIN.	ľ
	PITCH SCAS								
-	YAN SCAS								
	TIAN BEAD								
					1				H
	YAW RATE			- 11					
	PITCH RATE								
	ROLL ATTITU	DE.						nil.	
<u> </u>									
Щ.	YAW ATTITUDE								
``	PITCH ATTITUDE								
	5 6 2								
ECC	5 6 7	. 8	9						
milini									











No. 7 MINIGUN) FIRING																						
N 66-15285																						
APPROXIMATE DENISTY ALTITU	O£.	R	OTOF	-	- man	(CONF	16	JRA	TIO	N											
♣ F⊤. 2700				PM.	:		NSTI	3	ATAC	TAT	1001				NOT	- 5-6					1::	
						- Amount to the con-	*00 :			100 1101 101	done no morning			more throughough	TUE	RE	+ #	0517	iot	1		
c							44								ZE! FUL	T 0	MO	MUT N:EL	EY	ATI	ON	
			H				Н	+							MIN	E (100	O RO	UNI	3/1	HIQ IIN)	H
			HIE		II.				L						BAS	ED	ON	UN	ښ <u>ا</u>	BR/	ATE	Đ
				121	14		11	-					+	4	ENG	INE	01	TP	7	POW	ER	•
3															SH.	AF	H	OR.	EF	OWI	ER	
TIR IN														•	-		90,					
		-	-				ļ	+	-		-		+		1			#	+			
Topi							1			Ů,				П	Ξ.							
	al ne		-				14	-											+			
CAS							H	17				0										
														П								
			1-1-				1+						H	H			Н					
																			T			
							14	-										4	-			ij
ATE	1							F				2 1										
								Ī.														
		-			-													H		Н		
JDE 3dt			Pig 9																			
					H			F														
	111						H												H			i
							Ш															
					He		1						h				H					H
								1					H	1					4			
																		H	t			
							H															I
			,	1		100		+	70							Ш						i
SECONDS																						
					133111		100			1	1.4	HHE	1111				111	-41				






G) FIRING							
GIFIRING	and the same of th			and the contract to the contract of the contra			
265							
PROXIMATE SITY ALTITUDE	ROTOR	SPEED	CONFIG	MOITASUE			
2700	~R.	P.M.	INSTRU	MENTATION		NOTES :	
				OUTBOARD		TURRET	POSITION AZIMUTH
						ZERO ELE	FIRING AT HIGH
					1	DENSITY	ALT ITUDE IS M UNCALIBRATE!
						FREE AN	C TEMPERATURE OUTPUT POWER
					4	SHAFT H	MATELY 760 IORSEPOWER
a company of the comp	, , , , , , , , , , , , , , , , , , , ,				1	CONFIGU	KHIION
					;		
	age						
ROLL SO	EAS.		-14 15	72 3 d			
e gioner g wA	consum on a graduate of the second of the se				LITE		
-ROLL PATE					4		
)	YAW RATE				g v s san san s & graphic of street	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
Zp	ITCH RATE					Expenses to the second	
, , ,		The same states of the same of					
				Name against the second seconds			
	one to the state of the state o					, , , , , , , , , ,	
	1911			on many to post of the territory was as a sound of the territory			
				granger on go gle or and analysis that dealer in the distinct description of the confidence of the			
S. S. Santan d. S. Santan d. S. S. Santan d. S. S. Santan de Santa							
			and the second s	services of the property of the services of th			
5 6	7	8	9	10			
>\$							
			2				







IN)	FIRING																1	h. b.1									grape mate					
													And the state of t	-						1					en elle seed, region o							
DEN	PPROKIM JSITY A		יעדו	DE		F		OF ~		PEE	D		C	ÓИ	FIGU	JRA	TIC	N		and a man					A sup ex					ten no decom		
2	150	0						~	32	4			1		MUS			3				1	9	URR	RIGI	AT /	121	MUT	4.1			
STOP FIRING		Annual Property of the Parket		Annual state of the state of th	*** ** ** ** ** ** ** ** ** ** ** ** **				1 .							i canada		† =		:				ATI	ELE GON E (4	FIR	ING R	N.	DS/	IGH Mil	()	
STC			\$.				**************************************		e n ne en			e e e e	A comment of the comm						4	/ der as m	-		F	ASE REE NGI	0 0	R T OUT	NCA EM	PER T P	BRA LAT Pow	URE		
+-		and control of	4 	the same of the same of			in the same				-		and the second of the second o					1				5	5	HAF	T H	ORS	EF	941	ER			
			**	A man and a man and a man a ma				-								-		a so droop alfano		and regards or transcents.		1 moreona	4 -		4	- po so .			-			
		1		T value of			1								Ī					ner of a decay									April 1 Aug de la Company	E STATE OF S		
		1				and a second															-								The second second second	1		
											1		1			poster and a second	\$ 1 m-max 1															
-3		5			1								4									1										
	pana.	and the same state of the same											t t	4			grainage desi		Andreas Services	e trott y alle												
							1			edicehodo e od no	*	- M				And American Control of the Control			American designation of the second													
and the same of			, ,							* * * * * * * * * * * * * * * * * * *		1	printer for the second				!					* ** *****										
the section of the																																
																		alter fore the se														
-																				*												
	5			6			-				8			9	1 1 1 1 1 1	Production of the second of th	10	>				1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1										
ECC	DUDS														; ;	25				-										programme and the		














JO // MINIGUN) FIRING																		
66-15285																		
APPROXIMATE DENSITY ALTITUDE	R	оток	t sp	EED		CONF	GUR	ATIC	,									
1 FT.		~R	P.M.			NSTR				4		 NOT						
				Tale		PODS			Marine 1944	to table or to		70.	ARE'	AZI	TUM	H	9	
CYCLIC												MI	NIGU NEIT	W	FIRIT	IG !	SIN	LN)
								H				FA	SED	NA	TEM	PER	BRA	760
CLIC												64	PROS	HOR	SEP	200	K K	
4 2			H			H							NFIG	V (4)	17 10			
SCAS OF E					H	1							H					
	-			Н		Ш												
FOLL SCAS					H													
						,												
						T. La					H							
LYAW RATE	==																	
						İ												
-ROLL ATTITUDE					Ħ				H							ŀ		
PITCH ATTITUDE																		
YAW ATTITUDE				1111														
5 6	2			8		•		0										
COUDS																		
						2	7											












SUN) FIRING		
SURY PIRING		
283		
PPROXINATE NOTOR SPEED	CONFIGURATION	
7 FT. 7 RPM 3400 324		
	INSTRUMENTATION	NOTES:
	PCOS OUTBOARD	A TURRET POSITION
		FULL UP ELEVATION
		(#000 MOUNDE/MIN)
		ON UNCALIBRATED FREE AIR TEMPERATURE
		# NUME OUTPUT POWER
		APPROXIMATELY 760 SHAFT HORSEPOWER
		5 CONFIGURATION B
405		
UDE		
uōe		
4 5 6 7	8 9 10	
ECONDS		










No. 14 A MINIGUN) FIRI	inite in the second					
166-15283						
DENSITY ALTITUDE	ROTOR S	PEED	CONFIGUR	HOTTAS		
3.FT.	~RPI	A	INSTRUME		Notes:	
			PODS OUT	BOARD	A TURRET POSITION	
					POP RIGHT AZIMUTH	
					# MINIGUN FIRING AT HIGH RATE	
DINAL CYCLIC					S. DENSITY ALTITUDE IS BASED	
					AN UNCALIBRATED FREE	
					ENGINE OUTPUT POWER APPROXIMATELY 760	
				. 1 15 1	SHAFT HORSEPOWER	
ق ا					S. CONFIGURATION B	
FIRING						
5						
SCAS E						
- SCAS		444-1-	1-7-1-1-			
	برجانات أرجا	1 1 1 1 1 1 1		1-1-1-1		
7						
	-11-1-1-1-1-1-1					₩.
	-+					
ATTITUDE						
						Ш
						ш
4 5	6		1	10		₩
SECONDS						
				30		Ш















ure Na 16							
LAUNCHER) FIRING							
5/N 66- 15285							
TION DENSITY ALTITL	DE 20	TOR SPE	ED C	WFIGURA	МОТ		
3000		~RPM.					
				STRUMEN DOS OUT		NOTES	T POSITION
						ZERD.	ZINUTH PELEVATION
							Y ALTITUDE IS ON UCALIBRATED HA TENPERATURE
						3.ENGINE APPRO	OUTPUT POWER XIMATELY 750 HORSE POWER
							HORSE FOMER
- PITCH SCAS							
FIICH SCAS				A CAT - CONTROL OF CON			
				,			
- ROLL RATE			water to the state of the state				
4-1				- E. 83)			
			:	and all the second seco			
				1 1 1			
YAW ATTITUDE							
4 5 6				· · · · · · · · · · · · · · · · · · ·			
E ~ SECONDS							
				32			








No. 17					
CHER) FIRING					
√N 66-15285					
APPROXIMATE					
APPROXIMATE DENSITY AUTITU	~ RPN		IGURATION		
2800	324		RUMENTION	NOTES:	
		PODS	OUTBOARD	I.TURRET POSITION 90° RIGHT AZIMUTH FULL DOWN ELEVATION	
				2.DENS/TY ALTITUDE IS BASED ON UNCALIBRATED FREE AIR TEMPERATURE	
				BENGINE QUITPUT POWER APPROXIMATELY 760 SHAFT HORSE POWER	
T RING				4.CONFIGURATION B	
I I					
9072					
Š .					
L RATE					Ш
YAW RATE					
YAW ATTITLIDE					
IDE					
4 5 6		a 9	10		
BECONDS					
			<u> </u>		







N VU	NC+	e (ER)	FIR	INC	Ğ																																	
		1528																																				1
7			4	ATE													111																				117	-
	a	APPR		- cod color.	ידי	DE	5 .	RC	-	and the same of		-	E	>		C	Or	(F)	GL	1 R	1	(0)	1															
			2700	5					٠,	R. 32	4	٧.		1		II.	8-	T P	l IA	AF I	ит		VO.				417) T (Hill									
								1		;						P - FAST - 6	in seco	4.	de l'este	++ •	18	popular and		2000 100		l.	71	RR	****	P	381		1					1
																													04	MN	12111	EV	AT	101	4			
															-												D	NS!	0	ON	7	VE A	Lil		T	6	: : : : : :	-00 d - 00 d
																									reference of	J	ť							ow				
-	.;				1	-									-			I'										12P	7	HO	RS	EP	W	76. BR			Ti-	
					11.						1 1	1								1				-		•		10:	777	GU	₩A.	TIC	7	В				-
to the special of													-			,			1						10 db 100													日本 一日 一日
-			+	-		1							1	pro-	1					†		,					-		: ;						1111			Andrew & A.
-			:		1						1				:					į																		
			har and					 1				,			1				1					!		k e e												40.00
-	سنمب		1 :		!		· -	,			-		-															Lunge										10000
-		Apple	No.			1						1					-			į .				makes and a			1											1
-	. =	1		-			: -	 	y	••	•			•						-				1			-											1 1
					.,									4.8 81																						77	H	0.000
			L	4	1																			· Adameter						-			1111					1
1			A section of the sect	-				 				1				1										-												1
-				1			•										,	+																				1 1 1 1 1
and the same of the same of									7::																	1 - 1 - 1				7.1								
																										: :::					1111							
-					-															111													li E					
	1.																											1								Н		
-		-											i.						-	- , :-	1				-				i i i	-12							45	
-															-									1111														
+																										do o							11-11	1				
									1 2 2										1						11 9										##			1
																												F. 1-										
à																											10 0-0-1	17.1										1
Ť				-	-																			L		-												į
																														1.0								ļ
4			5		6			7	,				3			d	1		9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9	ı	9																	ļ
		SEC	- N-1	3																1.4																14114		1
															1.			3	1																			İ

٠







APPENDIX III FLIGHT RESTRICTIONS and OPERATING PROCEDURES

1. Limit Airspeed (V_{I.}):

Hog or alternate configuration - 180 KCAS below 3000 feet density altitude. Decrease 8 KCAS per 1000 feet above 3000 feet.

All other configurations - 190 KCAS below 4000 feet density altitude. Decrease 8 KCAS per 1000 feet above 4000 feet.

2. Gross Weight - Center of Gravity Envelope:

Forward limit - Below 7000 lb, fuselage station (F.S.) 190, linear decrease from F.S. 190 at 7000 lb to F.S. 192.1 at 9500 lb.

Aft limit - Below 7880 lb, F.S. 201.4. Linear decrease from F.S. 201.4 at 7880 lb to F.S. 200 at 9500 lb.

3. Sideslip Limits: 5 degrees at 190 KCAS. Linear increase to 20 degrees at 60 KCAS.

4. RPM Limits (steady state):

Power on - 6600 to 6400 engine rpm 324 to 314 rotor rpm

Power off - 304 to 339 rotor rpm transient lower limit 250 rotor rpm Power on during dives and maneuvers 319 to 324 rpm

5. Temperature and Pressure Limits:

Engine oil temperature	93°C
Transmission oil temperature	110° C
Engine oil pressure	25 - 100 psi
Transmission oil pressure	5 - 20 psi

6. T53L-13 Engine Limits - Installed:

Normal rated (maximum continous) Military rated (30 minute limit)	625° C
Starting and acceleration	675° C
(5 second limit) Maximum for starting and acceleration	760° C
Torque pressure	50 psi

APPENDIX IV PILOT'S RATING SCALE




Chart A-1. Sequential Pilot Rating Decisions.

CATEGORY	DEFINITION
CONTROLLABLE	CAPABLE OF BEING CONTROLLED OR MANAGED IN CONTEXT OF MISSION, WITH AVAILABLE PILOT ATTENTION.
UNCONTROLLABLE	CONTROL WILL BE LOST DURING SOME PORTION OF MISSION.
ACCEPTABLE	MAY HAVE DEFICIENCIES WHICH WARRANT IMPROVEMENT BUT ADEQUATE FOR MISSION. PILOT COMPENSATION, IF REQUIRED TO ACHIEVE ACCEPTABLE PERFORMANCE, IS FEASIBLE.
UNACCEPTABLE	DEFICIENCIES WHICH REQUIRE MANDATORY IMPROVEMENT. INADEQUATE PERFORMANCE FOR MISSION, EVEN WITH MAXIMUM FEASIBLE PILOT COMPENSATION.
SATISFACTORY	MEETS ALL REQUIREMENTS AND EXPECTATIONS; GOOD ENOUGH WITHOUT IMPROVEMENT. CLEARLY ADEQUATE FOR MISSION.
UNSAT I SFACTORY	RELUCTANTLY ACCEPTABLE. DEFICIENCIES WHICH WARRANT IMPROVEMENT. PERFORMANCE ADEQUATE FOR MISSION WITH FEASIBLE PILOT COMPENSATION.

Chart A-2. Major Category Definitions .

		SATISFACTORY	EXCELLENT, HIGHLY DESIRABLE	₹
	ACCEPTABLE ACCEPTABLE	MEETS ALL REQUIREMENTS AND EXPECTATIONS, GOOD ENOUGH WITHOUT IMPROVEMENT	GOOD, PLEASANT, WELL BENAVED	A2
	DEFICIENCIES WHICH WARRANT IMPROVEMENT, BUT ADEQUATE FOR MISSION.	CLEARLY ADEQUATE FOR Mission.	FAIR. SOME MILDLY UNPLEASANT CHARACTERISTICS. Good Enough for Mission Without Improvement.	A3
COMTROLLABLE	PILOT COMPENSATION, IF REQUIRED TO ACMIEVE ACCEPTABLE	UMSATISFACTORY RELUCTANTLY ACCEPTABLE.	SOME MINOR BUT ANNOYING DEFICIENCIES. IMPROVEMENT IS REQUESTED. EFFECT ON PERFORMANCE IS EASILY COMPENSATED FOR BY PILOT.	NY
CAPABLE OF BE: MG CONTROLLED OR MANAGED IN CONTEXT	PERFORMANCE, 1S FEASIBLE.	DEFICIENCIES WHICH WARRANT IMPROVEMENT. PERFORMANCE ADEQUATE FOR MISSION WITH	MODERATELY OBJECTIONABLE DEFICIENCIES. IMPROVEMENT IS NEEDED. Reasonable performance requires considerable pilot compensation.	A5
OF MISSION, WITH AVAILABLE PILOT ATTENTION		FEASIBLE PILOT COMPENSATION.	VERY OBJECTIONABLE DEFICIENCIES. MAJOR IMPROVEMENTS ARE MEEDED. REQUIRES BEST AVAILABLE PILOT COMPENSATION TO ACHIEVE ACCEPTABLE PERFORMANCE.	94
	UNACCEPTABLE Unacceptable		MAJOR DEFICIENCIES WHICH REQUIRE MANDATORY IMPROVEMENT FGR ACCEPTANCE. CONTROLLABLE. PERFORMANCE INAJEQUATE FOR MISSION, OR PILOT COMPENSATION REQUIRED FOR MINIMUM ACCEPTABLE PERFORMANCE IN MISSION IS TOO HIGH.	71.
	REQUIRE MANDATORY IMPROVEMENT INADEQUATE PERFORMANCE		CONTROLLABLE WITH DIFFICULTY. REQUIRES SUBSTANTIAL PILOT SKILL AND ATTENTION TO RETAIN CONTROL AND CONTINUE WISSION.	80
	MAXIMUM FEASIBLE PILOT COMPENSATION.		MARGINALLY CONTROLLABLE IN MISSION. REQUIRES MAXIMUM AVAILABLE Pilot skill and attention to retain control.	60
UNCONTROLLABLE CONTROL WILL BE	NCONTROLLABLE CONTROL WILL BE LOST DURING SOME PORTION OF MISSION.	OF MISSION.	UNCONTROLLABLE IN MISSION.	9

Revised Pilot Rating Scale

APPENIDIX V TEST INSTRUMENTATION

Flight test instrumentation was installed in the test helicopter by the contractor prior to the start of this evaluation. This instrumentation provided data from the pilot's panel, copilot/ gunner's panel, and oscillograph. The following instrumentation was calibrated by the contractor and approved by the USAAVNTA flight test engineer. The flight test instrumentation was maintained by the contractor throughout the test program. The following parameters were included in the instrumentation package:

a. Pilot's Panel

Standard system airspeed Standard system altimeter Collective stick position Normal acceleration Oscillograph counter Sensitive rotor tachometer

b. Engineer's Panel

Standard system airspeed Standard system altitude Turret azimuth Turret elevation Oscillograph counter Free air temperature

c. Oscillograph

Longitudinal cyclic stick position
Lateral cyclic stick position
Collective stick position
Directional control position
C.G. vertical accelerometer
Pitch, roll, and yaw attitudes
Pitch, roll, and yaw rates
Copilot/gunner's vertical acceleration
Altitude
Delta torque
Linear rotor speed
Turret position
Longitudinal, lateral, and directional SCAS actuator position

APPENDIX VI PHOTOGRAPHS




PHOTO 1-Front view of the XM-28 chin turret with the 40mm grenade launcher at left of photo and the 7.62mm automatic gun (M-134) on the right .



PHOTO 2 - AH-1G helicopter, depicting stow area for ammunition cans in side compartment and the oscillograph installation in wing pod .

Security	Class	sificatio

DOCUMENT CONTROL DATA - R & D .

(Security classification of title, body of ebstract and indexing annotation must be entered when the overall report is classified,

1. ORIGINATING ACTIVITY (Corporate author)

28. REPORT SECURITY CLASSIFICATION

UNCLASSIFIED

28. GROUP

US Army Aviation Test Activity (USAAVNTA) Edwards Air Force Base, California

ENGINEERING FLIGHT TEST OF THE AH-1G HELICOPTER EQUIPPED WITH THE XM-28 CHIN TURRET WITH ONE 7.62MM AUTOMATIC GUN (M-134) AND ONE 40MM GRENADE LAUNCHER (XM-129)-HYBRID, PHASE B. PART 5

4. DESCRIPTIVE NOTES (Type of report and inclusive dates)

AUTHOR(S) (First name, middle initial, last name William J. Connor, CV4, AV, US Army, Project Officer/Pilot Peter V. Passinisi, SP5, US Army, Project Engineer

. REPORT DATE 74. TOTAL NO. OF PAGES April 1968 46 SE. CONTRACT OR GRANT NO. SA. ORIGINATOR'S REPORT NUMBER(S) USAAVNTA 68-03 (66-06) USAAVCOM 68-03 9b. OTHER REPORT NO(S) (Any other numbers that may be assigned this report) N/A

10. DISTRIBUTION STATEMENT

US military agencies may obtain copies of this report from DDC. Other qualified users shall request through Hq, US Army Materiel Command, ATTN: AMCPM-IR, St. Louis, Missouri 63166

11. SUPPLEMENTARY NOTES

Commanding General
US Army Materiel Command ATTN: AMCPM-IR St. Louis, Missouri 63166

Part 5 of the AH-IG helicopter Phase B test was conducted at Yuma Proving Ground, Yuma, Arizona, from 6 through 9 February 1968 by the US Army Aviation Test Activity, Edwards Air Force Base, California. The test consisted of firing the XM-28 chin turret, with one 7.62 millimeter automatic gun (M-134) and one 40 millimeter grenade launcher (XM-129) to determine the weapons system's effect on the stability and control characteristics of the helicopter. No safety of flight restrictions resulted from firing this system within the flight envelope. Correction of four deficiencies is mandatory to provide acceptable mission effectiveness and safety. These deficiencies are the inadequate forward visibility from the pilot's cockpit due to the N-9A gunsight installation, the lack of a fire warning system, the lack of a standby generator for IFR flight, and link jam malfunctions of the minigun during symmetrical pull-out maneuvers. Fifteen shortcomings, for which correction is desirable, limit mission effectiveness. The reliability of the weapons system was questionable and service type testing should be conducted prior to system acceptance. Correction of the deficiencies is mandatory and should be tested prior to deployment. Shortcomings for which correction is desirable, should be corrected on a high priority basis.

DD FORM 1473 REPLACES DO PORM 1473, 1 JAN 64, WHICH IS

UNCLASSIFIED

Security Classification

INCLASSIFIED

KEY WORDS		LINKA			LINK		LINKC	
		ROLE	WT	ROLE	WT	ROLE	WT	
KM-28 Chin turret		1						
7.62 Millimeter automatic gun (M-13	4)	1					1	
O Millimeter grenade launcher (XM-	129)							
Stability and control characterists	.CS	î l			Ì			
Inadequate forward visibility		1						
Fire warning system		4			1			
IFR flight								
Link jam					i			
Reliability of weapons system								
							1	
							- 5	
				i l				
					İ			
							- 1	
			-				1	
			56	2	13	3	W 3	
							3	
				. 4				
			(5)				1)	
						4		
						9		
		П	10					
		[d	ch sa	8:			
					1			
		1						

UNCLASSIFIED
Security Classification

SUPPLEMENTARY

INFORMATION

DEPARTMENT OF THE ARMY

U.S. ARMY AVIATION SYSTEMS TEST ACTIVITY

SAVTE-AS Edwards Air Force Luse, California 93523 4 March 1969

SUBJECT: Change Number 1 to the USAAVNTA Project 68-03 (66-06)

Final Report.

SEE DISTRIBUTION

1. In accordance with unclassified message 12-1331 from AMSAV-R-FT, subject: AH-IG Phase B Test Reports - Control Positions, 13 December 1968, the following pen and ink changes will be made:

Engineering Flight Test of the AH-1G Helicopter Equipped with the XM-28 Chin Turret with one 7.62mm Automatic Gun (M-134) and one 40mm Grenade Launcher (XM-129) Hybrid, Phase B, Part 5, April 1968, (para 17, pg 8).

Add: The following:

 $\underline{\hbox{NOTE}}\colon$ The following applies to the aircraft dimensions and design information:

MAIN ROTOR

Collective:

Pitch full travel is 8.63 inches.

Stick:

Longitudinal full travel is 9.29 inches. Lateral full travel is 9.29 inches.

TAIL ROTOR

Directional:

Pedal full travel is 5.86 inches.

2. After the above change has been posted, this letter will be filed with the subject report.

FOR THE COMMANDER:

l Incl
Distribution

GERALD T. YAHIMO

CPT, INF

Acting Adjutant

INCLOSURE 1. DISTRIBUTION

Commanding General		Commanding Officer	
US Army Aviation Systems Command		US Army Aviation Materiel	
ATTN: AMSAV-R-FT	15	Laboratories	
AMSAV-R-EJ	2	ATTN: SAVFE-SO, M. Lee	1
AMSAV-C-AD	2	SAVFE-TD	2 1 1
AMSAV-L-F	1	SAVFE-AM	1
AMSAV-C-W	2	SAVFE-AV	1
PO Box 209		SAVFE-PP	1
St. Louis, Missouri 63166		Fort Eustis, Virginia 23604	
Commanding General		Commanding General	1
US Army Materiel Command		US Army Aviation Center	
ATTN: AMCPM-IR	5	Fort Rucker, Alabama 36362	
PO Box 209			
St. Louis, Missouri 63166		Commandant	1
		US Army Primary Helicopter	
Commanding General		School	
US Army Materiel Command		Fort Wolters, Texas 76067	
ATTN: AMCRD	2	roll wollers, leads 70007	
AMCAD-S	1	President	1
AMCPP	i		Т
		US Army Aviation Test Board	
AMCMR	2	Fort Rucker, Alabama 36362	
AMCQA	1		_
AMCPM-AI	5	Director	1
Washington, D. C. 20315		US Army Board for Aviation Accident Research	
Commanding General		Fort Rucker, Alabama 36362	
US Army Combat Developments			
Command		President	1
ATTN: USACDC LnO	11	US Army Maintenance Board	
PO Box 209		Fort Knox, Kentucky 40121	
St. Louis, Missouri 63166		,, ,, ,, ,, ,	
		Commanding General	
Commanding General		US Army Electronics Command	
US Continental Army Command		ATTN: AMSEL-VL-D	1
ATTN: DCSIT-SCH-PD	1	Fort Mormouth, New Jersey 07703	-
Fort Monroe, Virginia 23351	•	role no model, new Selsey 07705	
rott montoe, virginia 25551			
Commanding General		Commanding General	
US Army Test and Evaluation		US Army Weapons Command	
Command		ATTN: AMSWE-RDT	2
ATTN: AMSTE-BG	2	Rock Island Arsenal	_
USMC Ln0	ī	Rock Island, Illinois 61202	
Aberdeen Proving Ground,	-		
Maryland 21005			

Director	2	Commandant	1
US Marine Corps Landing		US Marine Corps	
Force Development Center		Washington, D. C. 20315	
Quantico, Virginia 22133			
,		US Air Force, Aeronautical	
Air Force Flight Test Center		Systems Division	
ATTN: FTBPP-2	5	ATTN: ASZTD	1
FTTE	2	ASNFD-10	1
Edwards Air Force Base,		Wright Patterson Air Force	_
California 93523		Base, Ohio 45433	
70320		200, 0	
Commander	1	Naval Air System Command	1
Naval Air Test Center (FT23)		Headquarters (A530122)	
Patuxent River, Maryland 20670		Department of the Navy	
		Washington, D. C. 20350	
Department of the Army			
Deputy Chief of Staff for Logistics		Federal Aviation Administration	
ATTN: LOG/MED	1	ATTN: Administrative Standard	
LOG/SAA-ASLB	ī	Division (MS-110)	2
LOG/OSALSCE	ī	800 Independence Avenue S.W.	-
Washington, D. C. 20310	•	Washington, D. C. 20590	
musilington, D. C. 20010		washington, D. C. 20370	
Department of Army	2	Defense Documentation Center	20
Army Concept Team in Vietnam		Cameron Station	
APO, San Francisco, California 96384		Alexandria, Virginia 22314	